




ERNIE FLETCHER
GOVERNOR

ENVIRONMENTAL AND PUBLIC PROTECTION CABINET

LJUANA S. WILCHER
SECRETARY

DEPARTMENT FOR ENVIRONMENTAL PROTECTION
DIVISION OF WASTE MANAGEMENT
UNDERGROUND STORAGE TANK BRANCH
81 C. MICHAEL DAVENPORT BLVD
FRANKFORT, KENTUCKY 40601-1190
www.kentucky.gov



September 14, 2005

ATTN CONNIE OWENS
GOODWIN BROTHERS INC
444 EAST MAIN STREET SUITE 101
LEXINGTON KY 40507

RE: Car Technologies
924 Winchester Rd.
Lexington - Fayette County
Incident #: 49525

AI#: 62183
UST ID#: 1060-034
UST System(s) Removal Date: July 13, 1998
Tank(s): #1 and 2: 4,000-gallon Gasoline tanks, #3 560-gallon Used Oil tank

NFA Keller

Dear Underground Storage Tank Owner:

The Division of Waste Management has reviewed the information received on November 23, 2004, the Classification Guide signed and certified on November 17, 2004, the information contained in the Closure Assessment Report signed on November 12, 1998, and any additional closure information received to date. These data indicate that no concentrations of hydrocarbon constituents for which you analyzed remain within the site above soil cleanup levels in Class III Soil Table 1 and groundwater cleanup levels specified in Table I (Maximum Contaminant Levels) of 401 KAR 42:070 and 080.

From your analyses, the Division agrees that this site has satisfied the requirements of Kentucky Revised Statutes 224.60-105 and Kentucky Administrative Regulation 401 KAR 42:070 and 42:080. Therefore, no further action is required, at this time, in response to a Closure Assessment request by the Division.

The Division has based this determination on information submitted by ATI/Shield Environmental and reserves all rights to require additional monitoring or testing and to take whatever action is necessary to protect public health and the environment if the Division determines there is need for further investigation.

NOTE: Proper disposal of all tank contents and liquid and solid wastes generated during this underground storage tank closure is the responsibility of the owner and the owner's contractor/consultant. The disposal of these wastes for this site has been verified by Karl Chance, P.E. # 200001. Disposal of these wastes has not been verified again by the Division.


02/06/2008 14:07 FAX 502-564-5981
Page 2
September 14, 2005
AI#: 62183
UST ID #: 1060-034

NOTE: All monitoring wells shall be properly abandoned in accordance with 401 KAR 6:310 within thirty (30) days from the date of determination that the monitoring well(s) are unsuitable for use as monitoring wells or within thirty (30) days of receiving a no further action letter from the Cabinet. If you have monitoring wells that are required for another investigation that is ongoing, then you may contact the Underground Storage Tank Branch to apply for a variance to this monitoring well abandonment requirement.

Payment of any outstanding underground storage tank fees is still required pursuant to KRS 224.60-150. Failure to pay any said outstanding fees may compromise the eligibility of the facility to receive reimbursement from the Petroleum Storage Tank Environmental Assurance Fund. If outstanding fees are due, the Underground Storage Tank Branch will contact you.

If you have any questions regarding this matter, please contact Douglas Graham of the Underground Storage Tank Branch at 800-928-7782 or 502-564-5981, ext. 275.

Sincerely,



Amy Siewert, AE1 Section Supervisor
Underground Storage Tank Branch
Division of Waste Management

AS/dg

ATTN MARK SWEET
SHIELD ENVIRONMENTAL
2465 FORTUNE DRIVE SUITE 100
LEXINGTON KY 40509